

#### State of Utah

## Department of Natural Resources

MICHAEL R. STYLER
Executive Director

# Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representative	es Present During the Inspection:	
Company	Dan Guy	
OGM	Joe Helfrich Environmental Scientist III	

### **Inspection Report**

Permit Number:	C0070016
Inspection Type:	PARTIAL
Inspection Date:	Thursday, November 17, 2005
Start Date/Time:	11/17/2005 9:30:00 AM
End Date/Time:	11/17/2005 3:00:00 PM
Last Inspection:	Wednesday, October 05, 2005

Inspector: Joe Helfrich, Environmental Scientist III

Weather: Sunny, clear, 45
InspectionID Report Number: 791

Accepted by: whedberg

12/9/2005

Permitee: MOUNTAIN COAL CO
Operator: MOUNTAIN COAL CO

Site: GORDON CREEK 2, 7 & 8 MINES
Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

#### **Current Acreages**

180.00	<b>Total Permitted</b>
34.88	<b>Total Disturbed</b>
	Phase I
	Phase II
	Phase III

	lineral C	<b>Ownership</b>	Types o	of Operations
--	-----------	------------------	---------	---------------

✓ Federal	Underground
State	Surface
☐ County	Loadout
<b>✓</b> Fee	Processing
Other	Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The purpose of this site visit was to conduct a partial inspection of the Gordon Creek reclaimed site. There are no amendments pending. There were no compliance issues or off site impacts noted during the inspection.

Inspector's Signature

Date

Tuesday, November 22, 2005

Joe Helfrich, Environmental Scientist III Inspector ID Number: 1

Permit Number: C0070016 Inspection Type: PARTIAL

Inspection Date: Thursday, November 17, 2005

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
   Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	<b>✓</b>		<b>✓</b>	
2.	Signs and Markers	<b>~</b>		<b>✓</b>	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	<b>V</b>		<b>✓</b>	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation	<b>✓</b>		<b>✓</b>	
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070016
Inspection Type: PARTIAL

Inspection Date: Thursday, November 17, 2005 Page 3 of 3

#### 1. Permits, Change, Transfer, Renewal, Sale

The permit for this reclaimed site was renewed effective August 28, 2004 and expires August 30, 2008.

#### 2. Signs and Markers

Signs with the required information were posted at the access to the reclaimed site. A number of the large rocks at the entrance to the reclaimed area had been painted orange apparently to emphasize no trespassing as the property is privately owned.

#### 4.b Hydrologic Balance: Sediment Ponds and Impoundments

There was a skiff of ice in the first cell of the sediment pond; the other two cells were dry.

#### 13. Revegetation

The reclaimed area has remained status quo since the previous inspection. Deer have continued to browse on the reclaimed site.